TOP SECRET 26 FEE	965 23 59z	
		1
PRECEDENCE ACTION DRICHTIME		117
INFO DTG		
25X1A FROM:	SPE	ECIAL INSTRUCTIONS
25X1A TO: (PRITY)	(ROUTINE)	25×1A
1. TAPED DEBRIEFING OF TANKER CREW NOW COMPL	ETE. PILOT	
BEBRIEFING HELD SHORTLY AFTER HE WAS RETURNED TO	BX	25 X 1A
BASE HELICOPTER AND SQUADRON DOCTOR. HQS,	AND LAC	25 X 1A
PERSONNEL PARTICPATED IN DEBRIEFING. EYEWITNESS RE	PORTS FROM	
TANKER CREW VERIFY PREVIOUS FINDINGS. FROM ALL REP		
UP AND BANK AFTER WHAT WAS DESCRIBED AS AN EXCEPTION	ONALLY FINE	
REFUELING WERE NORMAL FOR U-2. PILOT WAS ON 20 DEGI	REE CLIMIT AND	
20 DEGREES OF BANK AT MOMENT OF DISINTEGRATION (W	ORD	
DISINTEGRATION IS TANKER CREW'S TERMINOLOGY). ACCOM		
ARTICLE DISINTEGRADED INTO THEFE THREE LARGE PIECE		
		1
WINGS AND FUSELAGE) AND NUMEROUS SMALLER PEÉCES. AI		40
SUPPORT EQUIPMENT FUNCTIONED NORMALLY. PILOT REPORT	red minor	
OSCILLATION INSIDE THE COCKPIT BUT ENCOUNTERED NO I	DIFFICULTY IN	
ACTIVATING ANY OF THE EJECTION MECHANISM.	DATE	E TIME
	2	26 1600
2. ENGINE SECTIONS ONLY PARTS THUS FAR LOCATE	FE	
HAMPERED BY BAD WEATHER. GROUND SEARCH CONTINUING.	ENGINE PAGE	
D TYPED NAME AND TITLE PHONE R		
R L		25X1
A TYPED (OF STORM	ped) NAME AND TITLE	
E R		

Approved and/o	FEP REMARKS AND SHEET	KXA-RDP74B00447R	LASSIFICATION 098-4
PRECEDENCE	RELEASED BY	DRAFTED BY	PHONE

SECTIONS FOUND NINE MILES EAST SOUTHEAST OF TOWN OF LARAINE, WHICH IS APPROX 30 MILES EAST OF BAKERS FIELD, CALIF. AREA IS SPARSELY INHABITED AND HAVE HAD NO REPORTS OF AIRCRAFT PARTS BEING FOUND OR OF ANYING HAVING OBSERVED THE INCIDENT EXCEPT A FOREST RANGER WHO HAPPENED TO BE IN THE AREA AND REPORTED HE SAW THE ENGINE HIT THE GROUND.

- 3. HOSPITALIZATION WAS NOT NECESSARY FOR PILOT. APPEARS
 NO FRACTURES AND OTHER THAN NORMAL ACHES PILOT IN GOOD
 CONDITION.
 - 4. BASE SUPPORT IN ALL RESPECTS HAS BEEN EXCELLENT.

 END OF MESSAGE

CONTROL NO.	TOR/TOD	PAGE NO.	NO. OF PAGES	MESSAGE IDENTIFICATION	INITIALS
REGRADING INSTRUCTI	ONS			SECURITY CLASSIFICATION	

ACTION